

**RECEIVED**

APR 10 2014

**NMOCD ARTESIA**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

HMP1410423587

**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	CARIE STOKER
Address	415 W. WAIL ST. SUITE 500 274841	Telephone No.	432 664 7659
Facility Name:	DELHI	Facility Type:	BATTERY

Surface Owner	STATE	Mineral Owner		API No.	30-15-01594
---------------	-------	---------------	--	---------	-------------

**LOCATION OF RELEASE**

M	Section 28	Township 17S	Range 28E	Feet from the 330	North/South Line S	Feet from the 990	East/West Line W	County EDDY
---	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude 32.475668

Longitude -104.110687

**NATURE OF RELEASE**

Type of Release: PRODUCED WATER	Volume of Release: 15 BBLS	Volume Recovered: 15 BBLS
Source of Release: Broken nipple on pump suction line	Date and Hour of Occurrence: Apr 10, 2014; 2 PM Central Time	Date and Hour of Discovery Apr 10, 2014; 2:30 PM Central Time
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER via email	
By Whom? Carie Stoker	Date and Hour Apr 10, 2014, 5:25 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*  Cause of Problem: A nipple broke on the pump suction line Remedial Action Taken: Vacuum truck dispatched to remove any standing water (recovered 15 bbls)		
Describe Area Affected and Cleanup Action Taken.*  Area Affected: Leak affected area is within the battery containment wall		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

**OIL CONSERVATION DIVISION**

Signature: <i>Carie Stoker</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: CARIE STOKER		
Title: REGULATORY AFFAIRS COORDINATOR	Approval Date: 4/14/14	Expiration Date: NA
E-mail Address: carie@stokeroilfield.com	Conditions of Approval:	
Date: 4/10/2014 Phone: 432 664 7659	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:**

5/14/14

2RP 2254