

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

2RP-2249

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, LP	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No. (575)887-7329	
Facility Name: PLU-Big Sinks-35-24-30 USA # 1H	Facility Type: Exploration & Production	
Surface Owner: USA	Mineral Owner: USA	API No. 30-015-40155

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	35	24S	30E	360	North	1,980	West	Eddy

Latitude 32.180523° North Longitude 103.853389° West

NATURE OF RELEASE

Type of Release Crude oil and produced water	Volume of Release 10 bbls	Volume Recovered 1 bbl total fluid
Source of Release Open well casing valve	Date and Hour of Occurrence 2/28/14 at 7:30 a.m.	Date and Hour of Discovery 2/28/14 at 7:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.* The well had been shut in for repairs. The casing valve was accidentally left open when the well was put back on production. The valve was restored to a normally closed position.

Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 8,220 sq. of caliche well pad area and misted approximately 3000 sq.ft. of pasture area. All of the free standing fluid was recovered with a vacuum truck. The affected area was remediated as per NMOCD and BLM recommended guidelines. Please reference the attached *Remediation Summary and Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist		Approval Date: 4/25/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 4/24/14 Phone: 432-556-8730		Attached <input type="checkbox"/>	

Attach Additional Sheets If Necessary