

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

AUG 11 2009

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NJMW 1303150433

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	SWD 8" mainline (Skelly Area)	Facility Type	SWD Main waterline

Surface Owner	Federal	Mineral Owner		Lease No.	
---------------	---------	---------------	--	-----------	--

\*\*\*70 yards SW of Skelly Unit #46, Operator - Forrest Oil

LOCATION OF RELEASE

API #30-015-36964

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	22	17S	31E					Eddy

Latitude N 32° 49.296

Longitude W 103° 51.076

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	60bbls	Volume Recovered	20bbls
Source of Release	SWD mainline	Date and Hour of Occurrence	08/07/09	Date and Hour of Discovery	08/07/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD, Terry Gregston - BLM		
By Whom?	Kanicia Carrillo, Pat Ellis	Date and Hour	08/10/09 4:25pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Leak in the SWD mainline. Vacuumed up the water and repaired leak.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Castillo	Approved by District Supervisor:	Signed By 
Title: Regulatory Analyst	Approval Date: JAN 31 2013	Expiration Date:
E-mail Address: <a href="mailto:kcarrillo@conchoresources.com">kcarrillo@conchoresources.com</a>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/11/09 Phone: 432-685-4332	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

\* Attach Additional Sheets If Necessary

March 1, 2013

2RP-1535