<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Revised October 10, 2003

Form C-141

1220 South St. Francis Dr. side of form Santa Fe, NM 87505

	Release Notification and Corrective Action							
(250)		<b>OPERATOR</b>	₹	Initia	l Report	⊠ F	inal Repo	
	Name of Company COG Operating LLC	Contact Pat Elli						
	Address 550 W. Texas, Suite 1300 Midland, Texas 79701		Telephone No. (432) 685-4332					
4	Facility Name Southwest Central Tank Battery Facility Type Tank Battery							
	Surface Owner: Federal Mineral Own	ner	Lease No. NMNM-0467932					
	LOCATION OF RELEASE							
	Unit Letter   Section   Township   Range   Feet from the   N   O   20   17S   30E	Iorth/South Line   Fee	et from the East	/West Line	County	Eddy		
	Latitude N 32.81578° Longitude W 103.99519°							
	NATURE OF RELEASE							
(7598)	Type of Release: Produced Water	Volume of Relea			ecovered 98			
	Source of Release: 6" steel line	Date and Hour o 08/31/2010	f Occurrence		Hour of Disco	very		
353	Was Immediate Notice Given?							
(TA)	☐ Yes ☐ No ☐ Not Requi	red		regston -BL	M			
			Jim Amos-BLM Mike Bratcher-OCD					
	By Whom?	Date and Hour 08/31/2010 5:24 p.m.						
	Was a Watercourse Reached?  ☐ Yes ☒ No	If YES, Volume N/A	Impacting the Wa	tercourse.		_		
				RECE	IVED	7		
	If a Watercourse was Impacted, Describe Fully.*		i					
F	N/A AUG <b>2 3</b> 2013							
					NMOCD ABTESIA			
38A	Describe Cause of Problem and Remedial Action Taken.*		<u>L</u>	AlAir	ALLICANA	<u>.                                    </u>		
	Due to corrosion, a 6" steel water line developed a hole in it. A ½ inch plug was installed to repair the line and a new, plastic coasted line is being							
20	installed to replace the existing line.							
Describe Area Affected and Cleanup Action Taken.*								
	Tetra Tech inspected and assessed the spill area for extents. A work plan was prepared and submitted to NMOCD for approval. Soils exceeding the							
	RRAL were removed and transported to proper disposal. Once excavated to the appropriate depths, the excavation was backfilled with clean soil. Tetra Tech prepared closure report and submitted to NMOCD for review.							
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger							
	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability							
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other							
39	federal, state, or local and/or regulations.							
		OI	L CONSERV	ATION D	DIVISION			
- 1	Signature:	·		1	7	:		
		Approved by District	Approved by District Supervisor:			į		
Paragraph	Printed Name: Ike Tavarez (agent for COG)	Tulin						
	Title: Project Manager	nager Approval Date: 5/4/14 Expiration						
	E-mail Addresses like to some - Ottober - h	Conditions						
- 1	E-mail Address: ike.tavarez@tetratech.com	Conditions of Appro			Attached [	}	.	
,	Date: 6.70 / Phone: (432) 682-4559 Attach Additional Sheets If Necessary		Finer		300			
*	Attach Additional Sheets If Necessary				JKY-	47	3	