

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ **Final Report**

Name of Company: Nadel & Gussman HEYCO, LLC	Contact: Keith Cannon	
Address: PO Box 1936, Roswell, NM 88202	Telephone No.: 575-623-6601	
Facility Name: Rock Island 16 State 1H	Facility Type: Oil Well (Drilling) API No.: 30-015-38461	
Surface Owner: NMSU and NM	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section 16	Township 18S	Range 26E	Feet from the 2260	North/South Line North	Feet from the 1650'	East/West Line East	County Eddy
-------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Hydrocarbon and water.	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Wellhead blowout.	Date and Hour of Occurrence: 3/7/12 at approximately 1430	Date and Hour of Discovery: 3/7/12 at approximately 1430
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Keith Cannon	Date and Hour: 3/7/12 at approximately 1515	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.*	N/A	

RECEIVED

OCT 29 2013

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

History with subsequent report references as FRR status in support of this Final C-141.

The blowout occurred during the time NGH had opened the backside of the well and finding the well in a static condition, nipped down the wellhead in preparation to set the blowout preventer (BOP). The BOP was over the 2-7/8" tubing when the kick hit before it could be properly set due to a pressure increase that prevented it from being tightened down. Subsequently, the BOP did not seal on the flange due to the fact the bolts could not be securely fastened because of the high pressure fluid velocity coming out of the well. NGH contacted CUDD Well Control who is currently on location and has made their assessment of the well conditions. Following this, a fresh water mist system was set up over the wellhead to ensure reduced fire danger. Berms were pushed up to contain discharged fluids on location that will be hauled off by vacuum trucks to an authorized disposal site. Detailed environmental remediation will be implemented when the well is returned to normal operating status, due to safety concerns.

Describe Area Affected and Cleanup Action Taken.*

Refer to the Amended CAP of April 25, 2012 and the Final Remediation Report of September 17, 2013 that describes all remediation actions taken and their final dispositions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Keith Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Keith Cannon	Signed By <i>Mike Bratcher</i>	
Title: Drilling Superintendent	Approved by District Supervisor:	
E-mail Address: kcannon@heycoenergy.com	Approval Date: 5/8/14	Expiration Date: NA
Date: 17 September 2013 Phone: 575-623-6601	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1057