



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-JUNE-2014 Operator B P API #30-0 45-07767
Property Name LAUREL CANYON UNIT COM A Well No. 142 Location: Unit 0 Section 25 Township 29 Range 12
Well Status(Shut-In or Producing) Initial PSI: Tubing 80 Intermediate N/A Casing 125 Bradenhead 90

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			125		
10 min			125		
15 min			125		
20 min			125		
25 min			125		
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV DIST. 3

JUN 3 2014

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 18 INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN
TO NOTHING IN LESS THAN 15 SECONDS

By R. Ledesma
Heck
(Position)

Witness [Signature]

E-mail address _____