Form 3160-5 (August 2007) UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

JUL 1 4 2014

CONSERVATION

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	DECENTED
o not use this form for proposals to drill or to re-enter	ったにしここくてし

NMNM67102

abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRI	PLICATE - Other instruction	s on reverse side.		7. If Unit or CA/Agra NMNM131078	eement, Name and/or No.
1. Type of Well			· · · · · · · · · · · · · · · · · · ·	8. Well Name and No MultipleSee Att	
☑ Oil Well ☐ Gas Well ☐ Oth				<u>'</u>	acned
Name of Operator SM ENERGY COMPANY	E-Mail: VMARTINEZ@S	KIE MARTINEZ SM-ENERGY.COM		9. API Well No. MultipleSee A	Attached
3a. Address 3300 N A ST BLDG 7 STE 20 MIDLAND, TX 79705	0 Ph	Phone No. (include area code) : 432-688-1709 : 432-688-1701		10. Field and Pool, of PARKWAY	r Exploratory
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish,	, and State
MultipleSee Attached				EDDY COUNT	Y, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF N	NOTICE, R	EPORT, OR OTHE	ER DATA
TYPE OF SUBMISSION		TYPE OI	FACTION		
Notice of Intent	☐ Acidize	☐ Deepen	☐ Produc	tion (Start/Resume)	· □ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclam	nation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recom	plete	Other
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	□ Tempo	rarily Abandon	
	Convert to Injection	☐ Plug Back	□ Water	Disposal	
testing has been completed. Final Abdetermined that the site is ready for final SM is attaching information in extension date of 6/14/14 was. This also includes the well bell Lease Name UL:Sec:Townshi PARWAY 35 FEDERAL COM See attached.	inal inspection.) formation BLM requested on N given to SM by BLM. ow:	Notice of Written Order #1 n 377 530 FSL & 15 FEL (S	ACD53W. A(MUCE	NMOCD 1874 OR RECORD
14. I hereby certify that the foregoing is	Electronic Submission #24956	COMPAINY, sent to the C	arisbad	-	U OFFICE
Name(Printed/Typed) VICKIE M.		- · · (EER TECH	• -	
Signature (Electronic S	Submission)	Date 06/13/2	014		·
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE U	SE	
Approved By		Title	,	· · · · ·	Date
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conduct the applicant the applicant to conduct the applicant to conduct the applicant the applica	itable title to those rights in the subject operations thereon.	varrant or ect lease Office			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime statements or representations as to an	for any person knowingly and y matter within its jurisdiction.	willfully to m	ake to any department of	r agency of the United


Additional data for EC transaction #249567 that would not fit on the form

Wells/Facilities, continued

Agreement Lease NMNM131078 NMNM67102 NMNM67102

Well/Fac Name, NumberPARKWAY 35 FEDERAL COM 4H 30-015-39839-00-S1
PARKWAY 35 FEDERAL COM 5H 30-015-41377-00-S1

Location Sec 35 T19S R29E SWSW 450FSL 330FWL Sec 34 T19S R29E SESE 530FSL 15FEL 32.364000 N Lat, 104.031500 W Lon



Orifice Meter Test Report



Meter: 71877	6-00	-Parkway 35-4	H/6H	Date	Performed: Se	ptember 3, 2013	09:09 Rev. 2
	Energy	City:		State ID:	.*		
Division:		County:	Eddy	Federal ID:	. ,	•	
Area:		State:	New Mexico	API Code:			
Closing Group W22		Agency:	BLM	Latitude:	32.615780		
	3/2013	Reason for Test:	New Install	Longitude:	104.052775	Site Elevation:	
	_:						
•		Conditions		001		Constants	ACAD Date!
Differential:	Found 0.0	Left 00 0.00	Average 0.00	Calculation Method PSIA/PSIG:	PSIA	FPV Method: Blu:	AGA8-Detail 1191.60
				Contract Atmos, Pr	13.20	Specific Gravity:	0.68370
Pressure:	12.2		13.00	Pressure Base:	14.730	N2:	0.48600
Temperature:	67.0		85.00	Temp. Base:	. 60	CO2;	0.37200
EFM Flow Rate:	0.0	0.00					
Battery Voltage:				1			
				1			
	Meter	Inspection					
PrimBrand: Daniel	Model: S	Senior Ser	# 13140178				•
RTUBrand:Totalflox	v Model: 6	7213 Ser	#-T131010196				
DP Range: 0-250	Model: II	•	.,		· no c	alibration	
SP Range: 0-10				Standard	Found	Left	Flow Rate Error
Tmp Range: 0-200				Reset A.P.0	0.11		
	################################			Reset W.P.O No	0.11	0.00	
Static Location:	Upstream	Tap Typ	e:Flange	0.00	0.11	0.00	
Replace Seal Ring:	No	No Flow Cuto		50.00	50.17	50.00	0.17 %
replace deal rang.		NOT IOW Out	711. 0.40	175.00	175,39	175.00	D.11 ₀₄
				250.00	250,55	250.00	0.11%
	4			200.00 125.00	200.46 125.31	199.98 125.00	0.11%
				75.00	75.26	75.00	0.17%
		ce Plate		20,00	20.18	20.00	0.45%
Plate Size Existing	(- 2.0000			0.00	0.12	. 0.00	
Plate Size Found (d	r 2.0000	Ring Inspection: G	ood	4.00	4.16	4.00	1.98%
Tube ID Existing (D	r 3.0 680	Tube Serial: _				***************************************	
Distailassantad: Va	. Di-t- Ol	Vaa - Edua 01	Van Oille Nie		SP Ca	libration	
Plate Inspected: Yes	Plate Clean Smooth			Atmos. Press. Sour	ce: Measured	Obs. Atmos. Press:	13,10
_	Bevel			Standard (PSIG)	Found (PSIA)	Left (PSIA)	Flow Rate Error
	Bowed			0.00	12.80	13.10	-1.15%
	•	No Nicked	110	50.00	62.82	63,11	-0.22%
Plate Changed: Y	es			100.00	112.93	113.10	-0.08%
	New Plate	Size (dr)2.00	00				
							
					Temperati	re Calibration	
•				Standard	Found	Left	Flow Rate Error
				84,00	84.00	84.00	0.00%
				44.00	44.05	44.00	-0.06%
				74.40	74.20	74.40	0.13%
						Total Care	
Remarks: 1				·		Total Error:	
[
Witness:				Signed: Paul, A	illen B		-
	report are based	on spot averages and a	re not the values user			d volume calculations are r	performed in

% errors stated on this report are based on spot averages and are not the values used for volume corrections. Settlement % error and volume calculations are performed in external processes.

Powered by TEST!! (1) Copyright @ 2006-2014 Flow-Cal, Inc. Houston, Texas

May 13, 2014 15:02 - Page 1

Monthly Meter Analysis

4/1/2014



Meter #: 718776-00 Name: Parkway 35-4H/5H **Sample**Date: 03/21/2014

Type: Spot Pressure: Temperature:

40.0 98.0

H2O: H2S: lbs/mm 0 ppm

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide, CO2	0.3751		0.7587
Nitrogen, N2	2.2225		2.8615
Methane, C1	76.3137		56.2682
Ethane, C2	11.4422	3.0708	15.8131
Propane, C3	5.4070	1.4948	10.9582
Isobutane, iC4	0.7047	0.2314	1.8825
n-Butane, nC4	1.7545	0.5551	4.6869
Isopentane, iC5	0.4288	0.1574	1.4219
n-Pentane, nC5	0.4546	0.1654	1.5075
Hexanes Plus, C6+	0.8969	0.3928	3.8415
Water, H2O			-
Hydrogen Sulfide, H2S	0.0000	*	0.0000
Oxygen, O2	0.0000		0.0000
Carbon Monoxide, CO	•		
Hydrogen, H2			
Helium, He	0.0000		0.0000
Argon, Ar			

Property	Total Sample
Pressure Base	14.730
Temperature Base	0.00
Relative Density	0.7537
HV, Dry @ Base P.T	1278.55
HV, Sat @ Base P, T	1256.17
HV, Sat @ Sample P, T	
Fws Factor	
Cricondentherm	•
HCDP @ Sample Pressure	
Free Water GPM	
Stock Tank Condensate Brls/mm	
26 # RVP Gasoline	1.099
Testcar Permian	0.899
Testcar Panhandle	0.852
Testcar Midcon	0.733

Totals	100.0000	6.0677	100,0000

*** End of Report ***

WATER DISPOSAL ONSHORE ORDER #7

The following information is needed before your method of water disposal can be considered for approval.

1.	Farkway; Bone Spring
2	Amount of water produced from each formation in barrels per day.
3.	How water is stored on the lease. FIDERGLASS TANKS
4.	How water is moved to disposal facility. TVANSFER PUMPS
5.	Operator's of disposal facility a. Lease name or well name and number Parkway Pelaware Un to Station b. Location by % % Section, Township, and Range of the disposal system
	Unit J, NW/4SE14, Sec 35- T195-R29E
;	c. The appropriate NMOCD permit number 2-9821 and K-9822