

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*NAB14212331081*

OPERATOR

Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name: Dry Land Shiner Federal #1		Facility Type	Battery
Surface Owner : Federal	Mineral Owner: Federal	Lease No. (API#) 30-015-32815	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	3	T21S	R25E	940	North	660	East	Eddy

Latitude Longitude

**NATURE OF RELEASE**

Type of Release	Volume of Release	Volume Recovered
Oil	Oil 66 bbls	Oil 10 bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Tank developed a hole at the bottom seam	7/17/2014 4:00pm	7/17/2014 4:00pm
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mike Bratcher (OCD) / Jeffery Robertson (BLM)	
By Whom? Amanda Trujillo	Date and Hour 7/18/2014 11:17 am	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.\*  
A hole developed on a seam at the bottom of the tank. Hydrostatic pressure caused the hole to give and fluid rushed from the tank. All Fluid was contained with the bermed area.

Describe Area Affected and Cleanup Action Taken.\*  
All standing fluid was recovered and disposed of at an NMOCD approved facility. Saturated soil was hand excavated and disposed of at an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>7/31/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation Per O.C.D. Rule & Guidelines and like Approval by B.L.M.	Attached <input type="checkbox"/>
Date: -2014 Phone: 575-746-2010	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>8/31/14</i>	

\* Attach Additional Sheets if Necessary

*2RP-2406*

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

JUL 31 2014

RECEIVED