

New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

John Bemis
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Secretary

Jami Bailey
Division Director
Oil Conservation Division



Date 5/14/12

API # 30-0 15-38298

Dear Operator:

I have this date performed a Mechanical Integrity Test on the MUNCHEN FED #15

☒ If this test was successful the original chart has been retained by the NMOCD and will be scanned into the well's file in 7 to 10 days, pending receipt of the Form C-103 indicating the reason for this test. The well files are located at www.emnrd.state.nm.us/ocd/OCDOnline.htm

☐ If this test was unsuccessful the original chart has been returned to the operator pending repair and retest of the well, which must be accomplished within 90 days. If this is a test of a repaired well, previously in non-compliance, all dates and requirements of the original non-compliance are still in effect. No expectation of extension should be construed as a result of this test.

☐ If this test was for Temporary Abandonment include in your detailed description, on Form C-103, the location of the CIBP and any other tubular goods in the well, as well as your request for TA status.

☐ If this is a successful test of a repaired well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a detailed description of the repair to the well. Only after receipt of the C-103 will the non-compliance be closed.

☒ If this is a successful Initial Test of an injection well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a detailed description of the work done on this well including the position of the packer, tubing information and the date you began injection into the well.

If I can be of additional service contact me at (575) 748-1283 ext 107.

Thank You,

Richard Inge
Richard Inge
Field Inspector
District II - Artesia

