

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 28 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Linn Operating Inc. 2109324		Contact Brian Wall
Address 2130 W Bender Blvd Hobbs, NM 88240		Telephone No. 575-738-1739
Facility Name HE West B #30		Facility Type Injection
Surface Owner Federal	Mineral Owner	API No. 30-015-10705

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	09	17S	31E	1980	South	1980	West	Eddy

Latitude 32.84731 Longitude -103.87608

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 0
Source of Release Fiber glass pipeline	Date and Hour of Occurrence 08/26/2014	Date and Hour of Discovery 08/26/14 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson - BLM / Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 08/27/2014 0845	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* D&D Construction damaged injection line while backfilling a pipeline project. The lateral valve was shut and vacuum truck used to pull remaining fluid from line. After line was isolated. The following information was gathered. The Operators name was Jorge that was backfilling and broke the line. The Foreman on the job was Francisco, phone number 432-209-5581. Said that they would pay for repairs and will complete cleanup of location after our environmental department test soil. The D&D manager is Luis and his number is 432-209-4097. For Billing Purposes.

Describe Area Affected and Cleanup Action Taken.*

Directions to site: From intersection NM 360 and Eddy County 250 north on 250 for 1.2 mi, turn right to dirt road and follow for 1 mi to Y, stay left and follow road for .5 mi turn right and follow road for 1 mi, turn right follow road for .2 mi. , right for .8 mi. location is on left side. Leak is 100 yd. NE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Brian Wall		Approved by Environmental Specialist: 	
Title: Construction Foreman II		Approval Date: 8/29/14	Expiration Date:
E-mail Address: bwall@linnenergy.com		Conditions of Approval:	
Date: 08/28/2014 Phone: 806-367-0645		Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/29/14	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2462