

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1425893935

Name of Company <u>Legacy Reserves</u>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address <u>P.O. Box 10848 Midland Texas 79702-7848</u>		Contact <u>Jesse Garcia</u>		
Facility Name <u>Midnight Matador A 1</u>		Telephone No. <u>432-853-3535</u>		
		Facility Type <u>Wellhead</u>	<u>Battery - Flowline</u>	
Surface Owner	Mineral Owner	API No. <u>30-015-34385</u>		

LOCATION OF RELEASE

Unit Letter	Section 35	Township 17S	Range 27E	Feet from the 1896	North/South Line North	Feet from the 2000	East/West Line East	County Eddy.
-------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-----------------

Latitude 32.792723 Longitude 104-246997

NATURE OF RELEASE

Type of Release <u>Oil and Water</u>	Volume of Release <u>20 bbls</u>	Volume Recovered <u>5 bbls</u>
Source of Release <u>Flowline</u>	Date and Hour of Occurrence <u>8/25/ 2014</u>	Date and Hour of Discovery <u>8/25/14 7:00 AM</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Heather Patterson</u>	
By Whom? <u>Jesse Garcia</u>	Date and Hour <u>8/25/14 9:00 AM</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT


Describe Cause of Problem and Remedial Action Taken.*
Poly flow busted during lightning storm. Fluid was pick up, and flowline repaired

SEP 14 2014

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
A area of 60' X 80' was affected, some of the area had a light covering. All the area was picked up and taken to a state approved Facility. Fresh dirt was put in its place.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <u>Jesse Garcia</u>	Approved by Environmental Specialist: 	
Title: <u>Foreman</u>	Approval Date: <u>9/15/14</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>jgarcia@legacylp.com</u>	Conditions of Approval: Remediation per OCD Rule & Guidelines.	
Date: <u>9/10/2014</u>	Phone: <u>432-853-3535</u>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/15/14

2BP-2485