

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 22 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

Name of Company: BOPCO, L.P. <i>260737</i>		OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie
Facility Name: PLU-CVX-JV #027H. The spill is 1470 ft. S.W. of the well pad		Telephone No. 575-887-7329
		Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42111
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section 3	Township 25S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.162773 Longitude W 103.770594

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 bbls.	Volume Recovered: 5 bbls
Source of Release: 10" lay flat frac hose	Date and Hour of Occurrence: 9/15/14 at approximately 10:38 p.m.	Date and Hour of Discovery: 9/15/14 at approximately 10:38 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD in person to Heather while in the Artesia office	
By Whom? Tony Savoie	Date and Hour 9/16/14 at approximately 12:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A pickup truck operated by Baker Hughes backed over the frac hose creating a tear. The line was isolated and a section of hose was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The spill impacted approximately 1800 sq.ft. of caliche lease road and bar-ditch. A vacuum truck on-site recovered the free standing fluid.  
The remainder of the spill soaked into the road.  
The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>9/23/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>9/22/14</i>	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>10/23/14</i>	

\* Attach Additional Sheets If Necessary

2RP-2508