District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Ažtec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

				OPERA'		☐ Initi	al Report	\boxtimes	Final Repor				
Name of Co			Contact Chancey Summers										
		tanolind Rd.	NM 88240		Telephone No. (575) 397-8216								
Facility Nat	ne Patto	on 17 Federa			Facility Type Well location								
Surface Ow	ner BLI	wner	API No. 30-015-29824										
				T 0.0									
(1 6		T D			OF REI							
Unit Letter	er Section Township Range Feet from the No		North/	South Line	Feet from the	East/West Line		County					
N 17 24S 31E 330					South	1800	West		Eddy County, NM				
			1	Latitude <u>N 32.2</u>	1083°	Longitu	de <u>W 103.80130</u>	<u>)°</u>					
				NAT	URE	OF RELI	EASE						
Type of Relea	ase Skim	Volume of Release Volume Recovered											
					1 bbl oil, 8 bbls produced water 0 bbls								
Source of Rel		ffing box on v	eaked 		Date and Hour of Occurrence Date and Hour of Discovery 01/07/2014					overy			
Was Immedia	ite Notice C	If YES, To Whom? Mike Bratcher-NMOCD; Jennifer Van Curen- BLM											
By Whom?	Kathy Pur		Date and Hour 01/08/2014 @ 10:15 am										
Was a Watero					If YES, Volume Impacting the Watercourse.								
			No		NM OIL CONSERV						ATION		
If a Watercou	rse was Imp		J				RTESIA DI	STRICT	r				
JUL 2 2 2014													
									···	RECEIV	/CD		
Describe Caus	e of Proble	m and Remed	lial Action	Taken.*				``		KECEIV	בט		
The stuffing box on the well head leaked 1 bbl of oil and 8 bbls of produced water onto the ground. No fluids were recovered and the stuffing box issue was resolved.													
Describe Area	Describe Area Affected and Cleanup Action Taken.*												
		-											
The affected area is approximately 25' x 25' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD on 04/01/2014 and approved by Jennifer Van Curen of the BLM via email on 4/22/2014.													
I hereby certifi	I hereby cortify that the information given above is true and complete to the best of my brounded and understand that automate AR FOCD -11 1												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
1000000, 00000, 0							OIL CONS	FRV.	ATION I	TVISION	J		
Signature:													
Printed Name:	Chancey	A	Approved by Environmental Specialist: Audio										
Title: HES S	pecialist			A	oproval Date:	7/28/14	E	xpiration D	ate: No	1			
E-mail Address: Chancey.Summers@oxy.com						Conditions of Approval:							
	7-17	- 14						Attached					
Date:	Date: $(-10-19]$ Phone: (575) 397-8216 Final ttach Additional Sheets If Necessary												
Attaen Additte	mai Sheets	s it inecessai	T y							•		*	