

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: BOPCO, LP	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No. (575)887-7329
Facility Name: Remuda Basin Battery #1 Water Transfer Line Approximately 1,250 ft. East of battery.	Facility Type: Exploration & Production

Surface Owner: State of NM	Mineral Owner: State	API No. 30-015-03691
----------------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	24	23S	29E					Eddy

Latitude 32.288222° North Longitude 103.932289° West

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10 bbls	Volume Recovered None
Source of Release 3" poly line	Date and Hour of Occurrence 7/26/12 at approximately 9:00AM	Date and Hour of Discovery 7/26/12 10:00AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
APR 09 2014
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The 3" poly line split. The damaged section of pipe was replaced during initial response activities.

Describe Area Affected and Cleanup Action Taken.* Approximately 1800 sq.ft. of pasture was lightly misted at the release point. The fluid traveled down a caliche road, then exited the road into the pasture. Approximately 600 sq.ft. of road and approximately 960 sq.ft. of pasture was affected by the run-off areas. On April 18, 2012, during a site visit a few months prior to the release, it was noted that there had been several reports of illegal dumping of produced water by trucks traveling along the road from the Remuda Basin #1 Tank Battery to Rawhide Road. Based on this information and the fact that the road represents the only thoroughfare to several active production wells to the west of the release site, BOPCO requested and received NMOCD approval to leave impacted soil in the roadway in-situ. The affected area in the pasture was remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist		Approval Date: 8/1/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Final	
Date: 4/9/14	Phone: 432-556-8730	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1258