

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 10 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

NA 81428734858

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>LDL191D</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Lost Tank 3 Federal #15	Facility Type	Well

Surface Owner	Oxy	Mineral Owner		API No.	30-015-37951
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	3	22S	31E	2558	North	235	West	Eddy County, NM

Latitude N 32.42078° Longitude W 103.77349°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	6 bbls oil, 6 bbls produced water	Volume Recovered	0 bbls
Source of Release	Livestocked tampered and opened the 1" bleed valve on the well head	Date and Hour of Occurrence	09/15/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson- NMOCD, Sol Hughes- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/16/2014 @ 4:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Livestock tampered with and opened the 1" bleed valve on the well head spilling 6 bbls of oil and 6 bbls of produced water on to the ground. The valve was closed and a plug was installed.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 40' x 100' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by Environmental Specialist: <i>[Signature]</i>		
Title: HES Advisor	Approval Date: <i>10/14/14</i>	Expiration Date: <i>NA</i>	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: <i>10-10-14</i> Phone: (575) 397-8216	<p style="text-align: center;">Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>11/14/14</u></p>		

* Attach Additional Sheets If Necessary

2RP-254A