

NM OIL CONSERVATION
ARTESIA DISTRICT

DEC 03 2014

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
RECEIVED
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB14339531040 OPERATOR Initial Report Final Report

Name of Company: Chevron <i>4323</i>	Contact: Stephen Gwin
Address: 2401 Avenue 'O' Eunice, NM 88231	Telephone No.: (575) 263 - 0427
Facility Name: Indian Draw Tank Battery	Facility Type: tank battery
Surface Owner: BLM	Mineral Owner:
API: <i>30-015-20918</i>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	22S	28E					Eddy

Latitude: N 32° 23' 26.79" Longitude: W 104° 7' 27.90" *32-390775*
106-124417

NATURE OF RELEASE

Type of Release: produced water and oil	Volume of Release: ~13 bbls	Volume Recovered: ~11 bbls
Source of Release: valve was left open and fluid gravity fed to the ground	Date and Hour of Occurrence: 10/18/14 @ am	Date and Hour of Discovery: 10/18/14 @ 5:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Stephen Gwin	Date and Hour: 10/20/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

Depth to Water. ~25 ft bgs

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.* Approximately 13 bbls of produced water and oil were released when a valve was left open and fluid gravity fed to the ground. A vacuum truck was dispatched to pick up any free standing liquids. Approximately 11 bbls were recovered.

Describe Area Affected and Cleanup Action Taken.* Approximately 3,000 square feet of surface area was impacted by the release. This tank battery is scheduled to be replaced in February 2015 with construction of the new battery location currently underway. Chevron proposes the stained caliche in the area of the release be removed, hauled to state approved disposal facility, and replaced with clean caliche. Full remediation of the old tank battery area shall occur when the new tank battery comes online. At that time soil samples will be collected from the area and submitted to Cardinal Laboratories for testing. Upon receipt of laboratory analytical data from soil samples to be collected during delineation operations, EPI will prepare and present a Remediation Proposal for NMOCD approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Stephen Gwin</i>	OIL CONSERVATION DIVISION	
Printed Name: Stephen Gwin	Signed By <i>Mike Bratcher</i> Approved by District Supervisor:	
Title: HE Specialist	Approval Date: <i>12/4/14</i>	Expiration Date: <i>NA</i>
E-mail Address: stephen.gwin@chevron.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: _____ Phone: (575) 263-0427	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>1/4/15</i>	

* Attach Additional Sheets If Necessary
Site Ranky 20

2RP-2644