

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABK135727714

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Shoeless Joe 32 State #1H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-40586
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	19S	30E	990	North	300	West	Eddy

Latitude 32.6214477983968 Longitude -104.001831645152

NATURE OF RELEASE

Type of Release: Fire	Volume of Release: 0 bbls	Volume Recovered: 0 bbls
Source of Release: No release occurred	Date and Hour of Occurrence: 6:00 am 12/18/14	Date and Hour of Discovery: 6:00 am 12/18/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 12/19/2014 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED  
DEC 19 2014  
NMOCD ARTESIA



Describe Cause of Problem and Remedial Action Taken.\*

Fire originated in the area of the firebox of the heater treater, spreading and engulfing the piping around the vessel. The Otis and Happy Valley fire departments responded. By the time they arrived the fire was nearly out. The fire was out in a matter of minutes.

Describe Area Affected and Cleanup Action Taken.\*

The heater treater was the only damaged equipment. It will be repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 12/23/14	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: December 19, 2014 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

282-2652