

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 12 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB/501442511

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC 224137		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: Lee 3 Fee #6H		Facility Type: Battery	
Surface Owner: Fee		Mineral Owner:	
		API No. 30-015-41463	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	3	19S	26E	150	South	2310	West	Eddy

Latitude 32.6829279198928 Longitude-104.370861326883

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 2 bbl oil; 110 bbls PW	Volume Recovered: 1 bbl oil; 108 bbls PW
Source of Release: Piping Equipment	Date and Hour of Occurrence: 12/21/2014 8:00 am	Date and Hour of Discovery: 12/21/2014 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 12/22/2014 4:52 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" inch T on battery piping failed. Vacuum trucks were dispatched to recover all standing fluid and dispose of at an NMOCD approved facility. Repairs were made to the facility.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a facility constructed with a falcon liner. All lost fluid was able to be recovered and the facility put back into operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist.	
Title: Senior Environmental Coordinator	Approval Date: 1/14/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: January 12, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

ARP-2137