

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**NM OIL CONSERVATION**

ARTESTA DISTRICT

Form C-141

Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**JAN 21 2015**  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

*NA 1502354914*

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-450Y	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-42651	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	24S	30E	116	North	1524	East	Eddy

Latitude N 32.19633 Longitude W 103.56520

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release: 7 bbls	Volume Recovered: None
Source of Release: Flow line connection	Date and Hour of Occurrence: 1/15/15 Time unknown	Date and Hour of Discovery: 1/15/15 at approximately 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A hammer union on the flow line became loose. The union was re-tightened.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 1100 sq.ft. of pasture and pad area with a light mist of less than 1/2" saturation. It also puddled up in the pasture in an area measuring approximately 726 sq.ft. The BLM was notified the day of the release; an EPI remediation crew began removing the saturated soil on 1/16/15 and continued on 1/19/15, a total of 84 cubic yards of soil and caliche was hauled to Lea Land and clean soil was stockpiled on-site pending the out-come of the soil samples collected on 1/19/15. A Final C-141 and closure report will be submitted with the analytical data.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>1/23/15</i>	Expiration Date: <i>NA</i>
E-mail Address: tasavoie@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	Attached <input type="checkbox"/>
Date: <i>1/21/15</i> Phone: 432-556-8730	<b>PERMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

DATE: *2/23/15* *2RP-2758*