

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

JAN 26 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1502726789		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		260737		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220				Telephone No. 575-887-7329	
Facility Name: Legg Federal Tank Battery				Facility Type: Production Facility	
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-04734	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
B	27	22S	30E	660	North	2004	East	Eddy

Latitude N 32.369047 Longitude W 103.867870

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 18 bbls crude oil and 5 bbls PW	Volume Recovered: 3 bbls crude oil and 3 bbls PW
Source of Release: Heater-treater	Date and Hour of Occurrence: 1/24/15 time unknown	Date and Hour of Discovery: 1/24/15 at 4:00 a.m. approximately 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson, and Jim Amos	
By Whom? Tony Savoie	Date and Hour 1/24/14 at 11:42 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A gasket failed on the heater-treater fire tube. The production was diverted and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release pooled up in an area measuring about 1640 sq. ft inside the bermed area, and an area measuring approximately 5,750 inside the bermed area was misted with crude oil. All of the free standing fluid was picked up with a vacuum truck. The stained area will be left as is pending remediation. The impacted area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Signed By: <u>[Signature]</u> Approved by Environmental Specialist	
Title: Waste Management and Remediation Specialist		Approval Date: <u>1/27/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <u>1/26/15</u>	Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>2/27/15</u>	

* Attach Additional Sheets If Necessary

27-2761