

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

JAN 28 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*11AB15033A1472*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Graham Cracker 16 State #3H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-41633
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter B	Section 16	Township 26S	Range 28E	Feet from the 190	North/South Line North	Feet from the 1910	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.0492215718395 Longitude -104.09016327696

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 20 bbls	Volume Recovered: 15 bbls
Source of Release: Valve	Date and Hour of Occurrence: 1/4/2015 5:00 pm	Date and Hour of Discovery: 1/4/2015 5:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a failed auto-inlet motor valve. Vacuum trucks were dispatched to retrieve all standing fluid. Tanks were pressure washed and gravel was cleaned.

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within the lined facility. Repairs were made and clean-up completed. The facility is back in service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>1/30/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: January 28, 2015	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

*229-2175*