

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 23 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB 1505628052

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229131</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Jenkins B Federal #7	Facility Type: Wellhead

Surface Owner: Federal	Mineral Owner:	API No. 30-015-29451
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	20	17S	30E	1650	North	1090	West	Eddy

Latitude 32.8228242435965 Longitude -103.999198214662

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls Oil; 25 bbls PW	Volume Recovered: 4 bbls Oil; 24 bbls PW
Source of Release: Poly Flowline	Date and Hour of Occurrence: 1/30/2015 11:00 am	Date and Hour of Discovery: 1/30/2015 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jeff Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour: 1/30/2015 5:53 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when a weld failed on a poly flowline. Vacuum trucks were dispatched to recover the standing fluid and dispose of at an NMOCD approved facility. The flowline was repaired.

Describe Area Affected and Cleanup Action Taken.*
This release impacted the nearby pasture area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>2/25/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: February 23, 2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

REMITTANCE PROPOSAL NO
DATE: 3/25/15
ATER THAN: 287-2834