

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised August 8, 2011

MAR 9 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB15069291643

Name of Company: BOPCO, L.P. 200737		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie		
Facility Name: JRU-65 The flow line leak was 1700 ft. south of the well location.		Telephone No. 575-887-7329		
		Facility Type: Exploration and Production		

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27995
------------------------	------------------------	----------------------


LOCATION OF RELEASE

Unit Letter F	Section 6	Township 23S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	-----------------

Latitude N 32.335260 Longitude W 103.816507

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 13 bbls.	Volume Recovered: 8 bbls
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 2/28/15 time unknown	Date and Hour of Discovery: 2/28/15 at approximately 1:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The well had recently been cleaned out. Producing mostly water. The flow line developed a leak due to external corrosion; an emergency clamp was placed on the line. A section of flow line was replaced under the caliche road on 3/3/15.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 480 sq.ft of pasture and approximately 895 sq.ft. of caliche road. All of the free standing fluid was recovered with a vacuum truck. The stained area was left as is pending the final remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist		Approval Date: 3/10/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 3/9/15 Phone: 432-556-8730		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/10/15	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP.2872