

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

MAR 18 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1507934317		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC		Contact: Robert McNeill			
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077			
Facility Name: Down South State Com #4H		Facility Type: Battery			
Surface Owner: State		Mineral Owner:		API No. 30-015-37256	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	19	26S	28E	660'	South	330'	East	Eddy

Latitude 32.0222325672805 Longitude -104.119171023788

## NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls Oil	Volume Recovered: 20 bbls Oil
Source of Release: Tanks	Date and Hour of Occurrence: 2/23/2015 4:30pm	Date and Hour of Discovery: 2/23/2015 4:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused when paraffin built up in a transmitter, causing an alarm malfunction, which caused a tank to over flow. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was within the lined facility. All fluids were recovered, the facility was cleaned and put back in service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 3/20/15	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: March 18, 2015	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

2RP. 2898