

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 13 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1513453879 OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC <u>229137</u>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Com #31H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-40256
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	4	26S	28E	1580	North	2120	East	Eddy

Latitude 32.0745702926746 Longitude -104.090570698465

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 10 bbls Oil; 5 bbls PW	Volume Recovered: 9 bbls Oil; 3 bbls PW
Source of Release: Hole in Waterleg	Date and Hour of Occurrence: 4/20/2015 8:30 am	Date and Hour of Discovery: 4/20/2015 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
This release was caused by a hole in the water leg. Vacuum trucks were dispatched to recover the standing fluid.		
Describe Area Affected and Cleanup Action Taken.*		
This release occurred within a lined facility. Repairs were made to the water leg and the facility put back into service.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 5/14/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <u>Final</u> Attached <input type="checkbox"/>	
Date: May 13, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-3002