

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 01 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1519429994

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: CORSAIR STATE #002H	Facility Type: Facility

Surface Owner: State	Mineral Owner:	API No. 30-015-38062
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 2	Township 19S	Range 31E	Feet from the 480	North/South Line North	Feet from the 330	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.6954918018548 Longitude -103.832623313581

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 15 bbls	Volume Recovered: 14 bbls
Source of Release: Nipple of Dump Valve	Date and Hour of Occurrence: 6/16/2015 7:00 am	Date and Hour of Discovery: 6/16/2015 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a 1/4" nipple on a dump valve. Vacuum trucks were dispatched to recover any standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility and all fluid was able to be recovered. Necessary repairs were made; the facility was cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By  Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 7/13/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: June 30, 2015	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

2RP-3096