

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 14 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

**Name of Company:** BOPCO, L.P. *260737* **Contact:** Amy Ruth  
**Address:** 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 **Telephone No.:** 575-887-7329  
**Facility Name:** Indian Flats Bass Federal #4 at Indian Flats Bass Federal SWD (SWD is located 2996 ft. SW of Well #1 API 30-015-24968) **Facility Type:** Exploration and Production

**Surface Owner:** Federal **Mineral Owner:** Federal **API No.:** 30-015-22229

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	21S	28E	1652	South	2150	East	Eddy

Latitude 32.433934° Longitude -104.056149°

**NATURE OF RELEASE**

Type of Release: Crude Oil and Produced Water	Volume of Release: ¼ bbl oil, 5 bbls PW	Volume Recovered: None
Source of Release: Poly flow line	Date and Hour of Occurrence: 7/4/15 hour unknown	Date and Hour of Discovery: 7/4/15 8 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD) and Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour: 7/4/15 5:23 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Poly line ruptured by unknown cause. Poly line was clamped and the well was shut-in until the line was repaired.

Describe Area Affected and Cleanup Action Taken.\*  
The leak affected 525 square feet of pasture located just west of the Indian Flats Bass Federal SWD pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
	Signed By: <i>[Signature]</i> Approved by Environmental Specialist:	
Printed Name: Amy Ruth	Approval Date: 7/17/15	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: ACRuth@basspet.com	Attached <input type="checkbox"/>	
Date: 7/14/2015	Phone: 432-661-0571	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 8/20/15

2RP-3127

\* Attach Additional Sheets If Necessary