

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

APR 04 2013

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Lupe Carrasco
Address 104 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471
Facility Name NDDUP Unit #54	API Number 30-015-25645	Facility Type Plugged & Abandoned Well
Surface Owner Federal	Mineral Owner Federal	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	19	19S	25E	660	North	1980	East	Eddy

Latitude 32.6518200 Longitude 104.5214100

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 B/PW	Volume Recovered 5 B/PW
Source of Release Line Break	Date and Hour of Occurrence 3/15/13	Date and Hour of Discovery 3/15/13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (email)	
By Whom? Lupe Carrasco	Date and Hour 3/15/13 3:35 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Water line break due to normal wear and age of line, in addition to expansion of the line due to cool nights and warm days. Vacuum truck dispatched to recover produced water. Crew called to repair line.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 2' X 45'. Impacted soils to be scraped up and taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX, Chlorides will be run for documentation. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted. <b>Depth to Ground Water: &gt;100' (approximately 225', Section 19-T19S-R25E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: &gt;1000', SITE RANKING IS 0.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Lupe Carrasco</u>		OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco		Approved by District Supervisor: <u>[Signature]</u>	
Title: Environmental Regulatory Agent		Approval Date: <u>7/15/15</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>lcarrasco@yatespetroleum.com</u>		Conditions of Approval: <u>Final</u>	
Date: Wednesday, April 03, 2013 Phone: 575-748-1471		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-1594