

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 30 2015

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1521255814

274841

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ALAMO PERMIAN RESOURCES, LLC	Contact CARIE STOKER
Address 415 W. WALL ST. SUITE 500	Telephone No. 432 664 7659
Facility Name: HUMBLE STATE/SINCLAIR A ST	Facility Type: BATTERY

Surface Owner STATE	Mineral Owner	API No. 30-15-03005
---------------------	---------------	---------------------

LOCATION OF RELEASE

Section 19	Township 17S	Range 29E	Feet from the 1980	North/South Line S	Feet from the 452	East/West Line W	County EDDY
---------------	-----------------	--------------	-----------------------	-----------------------	----------------------	---------------------	----------------

32.49592
104.71195

NATURE OF RELEASE

Type of Release: OIL	Volume of Release: 56 BBLS	Volume Recovered: 45 BBLS
Source of Release: OIL TANK	Date and Hour of Occurrence: JULY 29, 2015; AM Central Time	Date and Hour of Discovery JULY 29, 2015; AM Central Time
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER via PHONE	
By Whom? Carie Stoker	Date and Hour JULY 29, 2015, 2:05 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Cause of Problem: Oil tank was struck by lightning
Remedial Action Taken: Vacuum truck dispatched to remove any standing oil (recovered 45 bbls); Scraped top soil with backhoe

Describe Area Affected and Cleanup Action Taken.*

Area Affected: Leak affected area extends outside of the battery containment wall to a nearby COG well

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Carie Stoker

Signature:

Approved by Environmental Specialist

Signed By Mike Bratcher

Printed Name: CARIE STOKER

Title: REGULATORY AFFAIRS COORDINATOR

Approval Date: 7/31/15

Expiration Date: N/A

E-mail Address: carie@stokeroilfield.com

Conditions of Approval:

Attached ☐

Date: 7/30/2015 Phone: 432 664 7659

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 9/3/15

* Attach Additional Sheets If Necessary

2RP-3177