

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1521727876

155615 OPERATOR

Initial Report Final Report

Name of Company: Nadel and Gussman Permian, LLC	Contact: Bill Dougherty
Address: 601 N. Marienfeld, Suite 508, Midland, TX 79707	Telephone No. 325-998-7107
Facility Name: Aid State #10	Facility Type: Oil Well
Surface Owner State of NM	Mineral Owner
API No. 30-015-38462	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	13	17 S	28 E	1650	NORTH	2310	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Water	Volume of Release N/A *	Volume Recovered 71.52 BBLS
Source of Release Manway Gasket Leak	Date and Hour of Occurrence 7/30/2015 Early Hours	Date and Hour of Discovery 7/30/2015 1:00 PM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson with the OCD	
By Whom? Bill Dougherty	Date and Hour 7/30/2015 2:00 PM MST	NM OIL CONSERVATION ARTESIA DISTRICT AUG 4 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Manway gasket was leaking on the heater treater.
A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015.

Describe Area Affected and Cleanup Action Taken.*

Approx. 5.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind.
A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation.

We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sarah Presley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sarah Presley	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Analyst	Approval Date: <i>8/5/15</i>	Expiration Date: <i>NA</i>
E-mail Address: spresley@naguss.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 8/4/2015 Phone: 432-682-4429	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *9/10/15* *2RP-3185*