District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Release Notification and Corrective Action

NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

All 6.28 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505 RECEIVED

DABLE	5243	3234	7			OPERAT	ΓOR		tial Report		Final Report
Name of Company						Contact					
Yates Petroleum Corporation						Chase Settle					
Address						Telephone No.					
104 S. 4 th Street						575-748-1471					
Facility Name						Facility Type					
Torpedo BOW State Com #1-H						Battery					
Surface Owner Mineral Owner						API No.					
State State						30-015-37495					
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Line	County		
M	11	25\$	27E	660'	:	South	330'	West	Eddy		ļ
	<u> </u>	L.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	L		<u> </u>						
Latitude_32.13895_Longitude104.03504_											
NATURE OF RELEASE											
Type of Release						Volume of			Volume Recovered		
Produced Water and Oil						15 B/O & I			15 B/O & P/W mix		
Source of Release Wellhead						8/15/2015;	our of Occurrence		Date and Hour of Discovery 8/15/2015; AM		
Was Immediate Notice Given?						If YES, To		0,13720	13/2013, 744		
☐ Yes ☐ No ☒ Not Required						d N/A					
By Whom?						Date and Hour					
N/A						N/A					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.					
The state of the s										# w	
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
Built up pressure caused the bone packing and the ram packing to blow out, causing the release. Vacuum truck(s) and roustabout crews were called.											
Describe Area Affected and Cleanup Action Taken.* An approximate area of 35' X 40' around the wellhead with a 40' X 10' finger running to the southeast. The wells were shut in, vacuum trucks were called											
							cavated soils wil				
							TEX (chlorides f				
TPH & BTEX are under RRAL's (site ranking is 20) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are											
above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: < 50' (approximately 45', Section 11, T25S-R27E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations a	ll operators	are required t	o report an	nd/or file certain	release no	otifications ar	d perform correc	tive actions for r	cleases which	may en	danger
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
]	10						OIL CON	SERVATION	<u> DIVISIO</u>	Ų	
Signature:											
						Approved by Environmental Specialist:					
Printed Name	e: Chase Se	ttle				reproved by Environmental operation.					
Title: NM Environmental Regulatory Agent						Approval Date: \$\\\31\\\5\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					
; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	r it mittelle	. regulatory	150III		+'	spinovai Dat	· MINITIO	LAPITATIO	i Daie.		
E-mail Addre	ess: CSettle	@yatespetrole	eum.com		(Conditions of	Approval:	Dulon & Gr	idedimend		
Date: A	27 2015		n	Dona: 575 740 4	1171	Conditions of Approval: Romediation per O.C.D. Rules & Guidelinesed 2ROBMIT REMEDIATION PROPOSAL NO					
Date: August * Attach Addi		ets If Necess		Phone: 575-748-4	+1/1 2	SUBMIT F	REMEDIATIO	3116	7		7111
amaon Addi		5 11 110003	··· <i>y</i>			LATER TH	IAN:IV	W111-J	2	_K[/-	1661