

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526632852

OPERATOR Initial Report Final Report

Name of Company Linn Operating Inc. 2109324	Contact E.L. Gonzales
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name JL Keel B #10	Facility Type Injection

Surface Owner Federal	Mineral Owner	API No. 30-015-05110
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 08	Township 17S	Range 31E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude 32.8544655 Longitude -103.8898849

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 0
Source of Release Valve	Date and Hour of Occurrence 09/14/2015	Date and Hour of Discovery 09/14/2015 5:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
SEP 18 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Received Call that water was shooting out of the injection well. Contractor company name is C&M Services

Describe Area Affected and Cleanup Action Taken.* Approx. 50ft by 50ft around the well head.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Approved by Environmental Specialist:	
Title: Production Supervisor	Approval Date: 9/23/15	Expiration Date: N/A
E-mail Address: elgonzales@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/17/2015 Phone: 505-504-8002	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/25/15

2RP-3283