Submit 3 Copies To Appropriate Office						Form C-103				
District I						WELL API NO.				
1625 N. French Dr., Hobbs, NM District II	625 N. French Dr., Hobbs, NM 87240 District II CONSERD VATION DIVISION						30-015-34356			
1301 W. Grand Ave., Artesia, NM 88210						5. Indicate Type of Lease				
District III 1220 South St. Francis D1.  1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505						STATE FEE x				
District IV 1220 S. St. Francis Dr., Santa Fe		Sunta 1 0, 1	1111 075	505		6. State 0	Oil & Gas I	Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS  I (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							7. Lease Name or Unit Agreement Name:			
DIFFERENT RESERVOIR. U									1	
PROPOSALS.)		•	·			8. Well N	ie 13 Fee	9		
1. Type of Well:		S.1	sian es		ED	8. Well N			Ì	
	/ell 🗶 C	Other	R	<b>ECEIV</b>	<u> </u>	A CCDIT	3H	<u> </u>		
2. Name of Operator			M	OV 09	7005	9. OGRII		_		
3. Address of Operator								7377		
P.O. Box 2267 Mid	and Moreag 70	702	QGI	D-ATTEBIA 10. Pool name or Wildcat  Cottonwood Creek; Wolfo					West Can	
4. Well Location	and, Texas /3	1702				COCCORIM	TOT CTOOL	C; WOLICAMD	, west Gas	
4. Wen Boomion									İ	
Unit LetterO	:660	feet from the	South	<u>:h</u> li	ine and	1980	_ feet from	the <b>Eas</b>	stline	
Section	13	Township 16		lange	2 <b>4</b> E	NMPM		County	Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)										
			3581	' GR	······································				CURSURAN MASS	
Pit or Below-grade Tank Appl										
Pit type Depth to G	oundwater	_ Distance from near	est fresh w	water well	Dis	tance from n	earest surfac	e water	_	
Pit Liner Thickness:	mil I	Below-Grade Tank: V	olume	bbls	; Constructio	n Material				
	Check Approp	riate Box to Inc	dicate N	Nature (		-				
					SUBSEQUENT REPORT OF:  EMEDIAL WORK					
							<u>.                                    </u>		_	
TEMPORARILY ABANDON		NGE PLANS			NCE DRILLI	NG OPNS.		PLUG AND ABANDON		
PULL OR ALTER CASING		TIPLE PLETION		CASING CEMENT	TEST AND JOB		X			
OTHER:				OTHER:						
13. Describe proposed or of starting any propos or recompletion.	completed operated work). SEE R	ions. (Clearly state ULE 1103. For M	all pertii Iultiple C	inent deta Completi	ails, and give ons: Attach	pertinent wellbore	dates, incluiagram of	iding estimate proposed cor	ed date npletion	
Cement 100 sx 245 sx	jts 8 5/8", 32 ed w/ 200 sx Pr prem Plus + 19 Prem Lite + 29	2 #, J-55 surfa rem Plus + 10 L % Thixset A + 1 % CACL2 + 5 LEM % CACL2, 14.8 p	EM Diam /4% Gil Gilson	nond Sea Isonite, nite, 12	al, 9.5 pp , 14.0 ppg 2.4 ppg, 2	, 1.53 cu .04 cuft,	ift/sx S			
185 sx prem Plus + 2% CACL2, 14.8 ppg, 1.34 cuft/sx tail slurry.  CIRC 183 sx 1st slurry, 63 sx 2nd slurry. WOC 18.25 hrs.  Tested casing to 2000 psi for 30 min. Test good.										
I hereby certify that the info	rmation above is	true and complete	to the be	est of my	knowledge	and belief.	I further c	ertify that any	pit or below-	
grade tank has been/will be cons	tructed or closed acc	ording to NMOCD gu	ıidelines [	,age	neral permit [	or an (att	ached) alteri	ative OCD-ap	proved plan	
SIGNATURE Stan	Wagne		_ TITLE		Regulator	y Analys	<u>ե</u> լ	DATE	11/7/05	
Type or print name Stan 1	Vagner		E-mai	iil addres	s:		Teleph	one No. <b>432</b>	686 3689	
For State Use Only	FOR RECO	ORDS ONLY		-				NOV 0	9 2005	

TITLE\_

\_\_\_\_\_ DATE \_\_

APPROVED BY\_\_\_

Conditions of Approval, if any: