Form 3160-5 (August 1999)

DEPARTMENT OF THE INTERIOR CONS. DIV-DIST. 2 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTED WELLS GRAND AVENUE

FORM APROVED OMB NO. 1004-0135

EXPIRES: NOVEMBER 30, 2000

| Do not use this form for proposals to drill or to re-enter an 10 88210 abandoned well. Use Form 3160-3 (APD) that the blood of the sales of the sale | | | | NM-NM94246 10109 4 6. If Indian, Allottee of Tribe Name | |
|--|---|-------------------|-------------|---|-------------------------------------|
| SUBMIT IN TRIPLICATE | | | | o. II IIIdiati, Allotte | e or mbe name |
| SUBMIT IN TRIFLICATE | | | | 7. Unit or CA Agreement Name and No. | |
| 1a. Type of Well Oil Well Gas Well Other | | | | | |
| | | | | 8 Well Name and No. | |
| 2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP | | | | Western Reserves Federal 3 9. API Well No. | |
| 3. Address and Telephone No. | | | | 30-015-30700 | |
| 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-235-3611 X4520 | | | | 10. Field and Pool, or Exploratory | |
| 4. Location of Well (Report location clearly and in accordance with Federal requirements)* | | | | Avalon (Upper Penn) Gas | |
| 1970' FSL 660' FWL Lot 32 Sec. 4 T21S R26E | | | | 12. County or Parish 13. State | |
| | | | | Eddy | NM |
| CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION | | | | | |
| | Acidize | Deepen | Production | (Start/Resume) | Water Shut-Off |
| ☐ Notice of Intent | Alter Casing | Fracture Treat | Reclamation | , | Well Integrity |
| ✓ Subsequent Report | Casing Repair | New Construction | Recomplet | te ily Abandon | ✓ Other placed on pump |
| Final Abandonment Notice | Change PlansConvert to Injection | Plug Back | Water Dis | - | |
| | | | | | |
| 3/2/2005 to 3/11/2005 Rigged up Key Energy unit. ND Tree, NU BOP. Released packer at 9346'. TOH with 2 3/8" tubing, guns and packer. Ran 312 jts 2 7/8" 6.5# L-80 tubing; seating nipple set at 9569' and end of tubing at 9624'. ND BOP, NU flange. Ran 2 1/2" x 1 1/4" x 24' x 28' RHBM-HVR pump, 146-1" fiberglass rods and 143-7/8" grade D rods. Hung well on. Rigged down Key unit. Plumbed well head, repaired and balanced Banta American 640-305-168 pumping unit, repaired Ajax DP-60 engine. 3/10/2005 returned to production. Tested at 14 BOPD, 129 BWPD, 250 MCFGD. | | | | | |
| Actequal Rox rector | rd - HindOCD | ALEXIS | D FOR | 2006 _0.c. | RECEIVED JAN 1 8 2006 OCD-ARTESIA |
| 14. I hereby certify that the foregoing is to Signed Candace R. & | rue and correct Name Title | Candace R. Grahan | | Date | 12/30/2005 |
| (This space for Federal or State Office use | | | 3 | | |
| | • | | | | |
| Approved by Conditions of approval, if any: | Title | | | Date | |
| | | | | | |