Submit 3 Copies To Appropriate District Office					
District I Energy, Minerals and Natural Resources 1625 M. French Dr., Hobbs, NM 88240			May 27, 2004 WELL API NO.		
District II	istrict II ON CONCEDIA TION DIVICION			30-015-29549	
District III	District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE F	EE 🗍	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV  Santa Fe, NM 87505		ı	6. State Oil & Gas Lease I	No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			Federal Lease – NM-05438	327	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name  Remuda Basin SWD		
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other SWD			8. Well Number	RECEIVED	
			1		
2. Name of Operator Devon Energy Production Company, LP			9. OGRID Number	JAN 8 0 2006	
3. Address of Operator			10. Pool name or Wildcat	CO-ARTES!	
P. O. Box 250 – Artesia, NM 88211-0250			SWD - Delaware		
4. Well Location Unit Letter D: 330 feet	from the North line and 660 feet	from the West line		···	
Section 20	Township 23S	Range 30E	NMPM Eddy	County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3153' GR					
Pit or Below-grade Tank Application  or Closure					
Pit type Depth to Groundwater	<del></del>	•	nce from nearest surface water_		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TO					
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   P AND A					
PULL OR ALTER CASING   N	MULTIPLE COMPL	CASING/CEMENT	JOB 🗌		
OTHER:		OTHER: Mecha	inical Integrity Test	1 1	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
Please see the attached chart fo	r the Mechanical Integrity Test	conducted on Decemi	ber 8, 2005. Tested to 500	psi for 30	
Minutes, held okay. NOTE: Notified Mike Bratcher w/OCD-Artesia of Mechanical IntegrityTest - did not witness.					
	. •				
		٠	¢		
			for the		
	•				
I hereby certify that the information aboursed tank has been/will be constructed or clos	ove is true and complete to the beed according to NMOCD guidelines [	est of my knowledge	and belief. I further certify the	at any pit or below-	
SIGNATURE Kusty Hen		Field Tech II	DATE December 9, 2		
Type or print name Rusty Klein	E-mail address:	rusty.klein@dvn.com	Telephone No. 505-7	48-3371	
For State Use Only	Jum C	armi Cinia	Maria de la companya	1-1-01	
APPROVED BY: Conditions of Approval (if any):		erry Guye	DATE •	2-0-4P	
, , , = operly ficial hispector					
District II - Artesia					

195 roundre sol through the region of the con-ROBERTO MONTA PRESIDENTE MONTA PROPERTY (MC) luctions Type of Leason off stomet. But he first. II sat II itani. Marentana normali SCHOOL FREE MANY STREET TERRITORY CONSTRAINT College Manne on Unit Aggregation Notice JAN 3 0 ZEIR A PATRICIA P. M. GRAPHIC CONTROLS CORPORATION BUFFALO, NEW YORK 18-8-05 MITTOST Rumuda Basin metro a de colegat cabes, o cul-I may for a questi ni car con sic floodin. NOON 分類 建油油炉 可一 的现在 า และสาราธิ และ เกาะ เปลี่ยว และ เกาะ และสาราธิการสาราธิการและสาราธิการและ Gerry Guye
Deputy Field Inspector

District II - Artesia

