Submit 3 Copies To Appropriate District Office	State of Ne Energy, Minerals and			Form C-103
District I	Energy, wither as and	Natural Resources	WELL API NO.	May 27, 2004
District II			30-015-02231	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, N	NM 87505	STATE X I	FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 8750	5		6. State Oil & Gas Lease E-7668	No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Ag East Millman Pool Unit 8910169240	
1. Type of Well: Oil Well X Gas Well	Other		8. Well Number	
2. Name of Operator	Offici	RECEIVE:	9. OGRID Number	
Stephens & Johnson Operat	ing Co.	FFR 1 6 2006	019958	
3. Address of Operator	<u></u>	UUU-ANTROM	10. Pool name or Wildcat	
P.O. Box 2249, Wichita Fa 4. Well Location	lls, TX 76307-2249	SAR WILLIAM	Millman Yates-SR-QN-G	<u>iB-SA, East</u>
Unit Letter:	2310 feet from the	South line and	660 feet from the_	West line
Section 13	Township 19	S Range 28E	NMPM Cour	nty Eddy
11 TO 12 TO		ether DR, RKB, RT, GR, et GR 3383'		
Pit or Below-grade Tank Application X	or Closure 🗆			
Pit type WK OVT Depth to Groundwater		st fresh water well <u>3500'</u> Dis	stance from nearest surface water	r <u>4000'</u>
Pit Liner Thickness: 12 mil	Below-Grade Tank: Vo	olume 700 bbls; Construction	on Material	
12. Check ANOTICE OF INT PERFORM REMEDIAL WORK [X]	ENTION TO:	SUB	, Report, or Other Data SSEQUENT REPORT ☐ ALTE	
TEMPORARILY ABANDON	CHANGE PLANS [G AND
PULL OR ALTER CASING	MULTIPLE [COMPLETION	CASING TEST AND CEMENT JOB		NDONMENT
OTHER:	Γ	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
See Attachment				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X , a general permit or an (attached) alternative OCD-approved plan				
SIGNATURE WILL M.	Lucara	TITLE Petroleu	m Engineer DATE	2-15-2006
Type or print name	ncaid	E-mail address:	mkincaid@sjoc.net Telephone N	To. (940) 723-2166
	IM W. GUM			FEB 1 7 2006
APPROVED BY	· # SUFERVIOUR	_ TITLE	DATE _	
Conditions of Approval, if any:				

Page 2 (C-103 Attachment)

East Millman Pool Unit No.7-4 has a packer stuck in the hole at a depth of 1971'. The following remedial work is for removing the packer.

- 1. TOH with rods and pump.
- 2. Try to unseat packer.
- 3. If cannot unseat packer, cut off tubing above packer and TOH with tubing.
- 4. TIH with mill and tubing and mill over packer.
- 5. TOH with tubing and mill.
- 6. TIH with tubing pump and rods.