

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABI5282A0224 OPERATOR Initial Report Final Report

Name of Company	RKI E&P, LLC	Contact	Taylor Jones
Address	210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No.	405-996-5782
Facility Name:	Ross Draw Unit 34	Facility Type :	Oil and Gas Well
Surface Owner:	Federal	Mineral Owner:	Federal
		API No.	30-015-41578

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	26S	30E	600	FNL	435	FWL	Eddy

Latitude: 32.0336418 Longitude: -103.8763428

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	70 Bbbs	Volume Recovered:	55 Bbbs
Source of Release:	Surface Poly line	Date and Hour of Occurrence	10/6/15 - 0300hrs MT	Date and Hour of Discovery	10/06/15 - 0300hrs MT
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker (BLM)		NM OIL CONSERVATION ARTESIA DISTRICT	
By Whom?	Zack Laird	Date and Hour: 10/07/15 - 1130hrs			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.		OCT 07 2015	
If a Watercourse was Impacted, Describe Fully.*		N/A		RECEIVED	

Describe Cause of Problem and Remedial Action Taken.*
A poly line carrying natural gas parted and caught fire on the ROW which has 2 other gas lines and 5 poly water lines on it which in turn melted the water lines causing the produced water release

Describe Area Affected and Cleanup Action Taken.*
Produced water spill remained on pipeline ROW, affecting a 25'x25' area. Gas to poly line was shut in allowing fire to extinguish. Vac truck dispatched to recover all standing produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Taylor Jones	Approved by Environmental Specialist:	
Title:	EHS Systems Specialist	Approval Date:	10/9/15
E-mail Address:	Tjones@rkixp.com	Expiration Date:	N/A
Date:	10/07/15	Phone:	405-996-5782
		Conditions of Approval:	Attached <input type="checkbox"/>
		Remediation per O.C.D. Rules & Guidelines	

Submit Remediation Proposal no later than: 11/13/15

2RP-3322

* Attach Additional Sheets If Necessary