

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

SEP 26 2008  
OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**NAB1528834107**

**OPERATOR**

Initial Report

Final Report

Name of Company <b>OXY USA</b>	<b>192403</b>	Contact <b>Kelton Beaird</b>
Address <b>102 S Main Carlsbad, NM 88220</b>		Telephone No. (O) <b>505-887-8337</b> C) <b>575-390-1903</b>
Facility Name <b>Big Walt disposal line</b>		Facility Type <b>Disposal Line</b>
<b>30 015 33315</b>		

Surface Owner <b>BLM</b>	Mineral Owner	Lease No.
--------------------------	---------------	-----------

**LOCATION OF RELEASE**

**API No. 30-015-33315**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<b>1</b>	<b>22s</b>	<b>24e</b>					<b>EDDY</b>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**



Type of Release <b>Produced Water</b>	Volume of Release <b>90-100bbbls</b>	Volume Recovered <b>none</b>
Source of Release <b>Disposal Poly-Line</b>	Date and Hour of Occurrence <b>unknown</b>	Date and Hour of Discovery <b>9-17-08/ 4:00pm</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jim Amos-BLM Sherry Bohnam-NMOCD</b>	
By Whom? <b>Kelton Beaird- Oxy HES</b>	Date and Hour <b>See above</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Overpressure in the line caused the line to bust releasing fluid into the pasture, across the road, continued down the road

Describe Area Affected and Cleanup Action Taken.\*  
The area in the pasture affected was approx. 50' wide by 300' long before branching into smaller streams and running down the road, eventually turning into one small stream and ending. Per BLM and NMOCD permission, this water has a 998ppm chloride level. Therefore this area will be monitored continuously to assure that proper vegetation continues.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kelton Beaird</b>	Approved by District Supervisor: 	
Title: <b>HES Specialist</b>	Approval Date: <b>10/15/15</b>	Expiration Date: <b>NIA</b>
E-mail Address: <b>kelton_beaird@oxy.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>9-18-08</b>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: **11/15/15**

**ARP-3334**