

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NA61529941728

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Diamond PWU 22-5H	Facility Type	Oil

Surface Owner State	Mineral Owner State	API No.	30-015-40822
---------------------	---------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	19S	29E	725	North	330	West	Eddy

Latitude: N 32°55'14.21"

Longitude: W 104°06'96.26"

NATURE OF RELEASE

Type of Release Spill Produced Water and Oil	Volume of Release 6 bbls oil and 4 bbls water	Volume Recovered 3 bbls oil and 2 bbls produced water
Source of Release Frac Tank over flowed	Date and Hour of Occurrence 10/22/2015 @ 11:20 AM	Date and Hour of Discovery 10/22/2015 @ 11:20 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher OCD	
By Whom? Jesse Armendariz, Assistant Production Foreman	Date and Hour 10.22.2015 @ 11:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A


Describe Cause of Problem and Remedial Action Taken.*

Frac tank burped causing a 6 bbl oil and 4 bbl produced water release. Well was immediately shut in to prevent further release.

Describe Area Affected and Cleanup Action Taken.*

6 bbls oil and 4 bbls produced water was released on the North, North West side of the facility. 3 bbls oil and 2 bbls produced water was recovered via vacuum truck. The affected area was a 100 x 50 and all released fluid remained on location. Environmental Agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 10/26/15	Expiration Date: N/A
E-mail Address: corina.moya@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/22/2015 Phone: 575.746.5559	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/24/15

2RP-3352