

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1530140875*

**OPERATOR**  Initial Report  Final Report

Name of Company Cimarex Energy <i>215009</i>	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Hornsby 35 Fed 3H	Facility Type production

Surface Owner Federal	Mineral Owner	API No. 30-015-42208
-----------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	35	26S	27E	210	S	1310	W	Eddy

Latitude 32.0005684 Longitude -104.1651154

**NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 59 bbls	Volume Recovered 55 bbls
Source of Release 4" poly flow line	Date and Hour of Occurrence 7/26/15	Date and Hour of Discovery 7/26/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 7/27/15 1:33 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION  
ARTESIA DISTRICT  
OCT 27 2015**

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\*  
Poly line ruptured due to pressure. 45 bbls were contained within a lined containment and were recovered. 14 bbls were on location pad just outside of containment and 10 bbls were recovered.

**RECEIVED**

Describe Area Affected and Cleanup Action Taken.\*  
Environmental consulting company (Diversified) will be on location to sample and develop work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Supervisor	Approval Date: <i>10/28/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: calderman@cimarex.com	Conditions of Approval: O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 7/30/15 Phone: 432-853-7059	<b>SUBMIT REMEDIATION PROPOSAL NO</b> LATER THAN: <i>11/20/15</i>	

\* Attach Additional Sheets If Necessary

*2RP-3359*