<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District III

District III

District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

AUG 2 6 2010 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form NMOCD ARTESIA

30-015-02648 Release Notification and Corrective Action Release # 1 of 3									of 3			
MCB1028134092						OPERA?			✓ Initia	ıl Report	Final Report	
						Contact Marty Bloodworth, PE						
						Telephone No. (432) 897-0673 Facility Type Frac Tank						
Surface Owner Mineral Owner						Lease No. B-11539						
				LOCA	TIO	OF RE	LEASE					
Unit Letter E	Section Township Range Feet from the North				South Line North	Feet from the 990	East/West Line West		County Eddy			
Latitude 32 d 45 m 45.1 s Longitude -104 d 12 m 9.41 s												
NATURE OF RELEASE												
Type of Release Produced water							Volume of Release Unknown Volume Recovered Unknown					
Source of Release Frac Tank Was Immediate Notice Given?							Date and Hour of Occurrence Date and Hour of Discovery see below If YES, To Whom?					
Yes No Not Required												
By Whom?						Date and Hour						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
The West Artesia Grayburg Unit #4, which is an injection well, was being flowed back to a frac tank in preparation for a repair of the well.												
Sometime between the close of business on 07/20/2010 and the morning of 07/21/2010 the tank overflowed. The tank was drained and the water flow was stopped. Preliminary cleanup was done pending the testing to determine the extent of the damage.												
1. Francisco de la companya de la co												
	Describe Area Affected and Cleanup Action Taken.*											
Water ran across the well pad, down portions of the entrance road to the well and into the adjacent pasture. The pad, pasture, and road will be tested and a formal remediation plan submitted.												
testeu anu a		negiation pia	ii subiiitt	cu.								
I hereby certi	fy that the	information gi	ven above	is true and comp	lete to the	he best of my	knowledge and u	ındersta	nd that purs	suant to NM	OCD rules and	
regulations al	ll operators	are required t	o report ar	nd/or file certain r	elease n	otifications a	nd perform correc	ctive act	ions for rel	eases which	may endanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,	or local la	ws and/or regi	ilations.		1		OIL CON	CEDI	/ A TION	DIVISIO)NI	
and the							OIL CONSERVATION DIVISION					
Signature: //////						Signed R. While Keep						
Printed Name: C. M. Bloodworth, P.E.						Approved by District Simple Str. Mile Brance						
Title Vice P					Approval Da			Expiration	Date:	1		
E-mail Address: martyb@alamoresources.com							Conditions of Approval Remediation					
						Conditions of Approval: Remediation Per NMOCD Rules & Guidelines Attached						
Date:	08/26/20:			hone: (432)897-	673	· · · · · · · · · · · · · · · · · · ·			<u> </u>			
Attach Addi			агу		K	emediati	n proposac	- Di	16	21	YP-444	
PMGB10	42133	124				11/8	110				# / _	