

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1531456099*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: LOCO HILLS SWD 35 #001	Facility Type: SWD
Surface Owner: State	Mineral Owner:
API No. 30-015-31635	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	17S	30E	660'	South	860'	East	Eddy

Latitude 32.7856102 Longitude -103.9196548

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 500 bbls PW	Volume Recovered: 500 bbls PW
Source of Release: Plugged discharge line	Date and Hour of Occurrence: 10/15/2015 7:00 pm	Date and Hour of Discovery: 10/15/2015 7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Fri 10/16/2015 5:07 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**

If a Watercourse was Impacted, Describe Fully.\*  
ARTESIA DISTRICT  
NOV 06 2015

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a plugged discharge line. Vacuum trucks were dispatched to recover all standing fluid.

**RECEIVED**

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within a lined facility. All fluid was able to be recovered, repairs made the facility put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>H...</i>	
Title: Senior Environmental Coordinator	Approval Date: 11/10/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: October 29, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

*2RP-3380*