

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1531457125

303900

OPERATOR

Initial Report Final Report

Name of Company	Memorial Production Operating LLC	Contact	Heather Dolphin
Address	500 Dallas Street Houston TX 77002	Telephone No.	832-797-1334
Facility Name	North Square Lake Unit #197	Facility Type	Well
Surface Owner	Mineral Owner	API No. 30-015-33065	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	20	16S	31E					Eddy

Latitude 32.9031677 Longitude -103.8998642 NAD 83

NATURE OF RELEASE 1bbl Oil/ 10bbbls PW Obbls

Type of Release	Produced Water	Volume of Release	<u>10/29/15</u>	Volume Recovered	
Source of Release	Flowline	Date and Hour of Occurrence		Date and Hour of Discovery	11:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson & Mike Bratcher, OCD Shelly Tucker & Art Arias, BLM		
By Whom?	Heather Dolphin	Date and Hour	10/29/2015 5:08pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 04 2015

RECEIVED



If a Watercourse was Impacted, Describe Fully.*
n/a

Describe Cause of Problem and Remedial Action Taken.*
Poly line blew a hole due to closed valve at header, the line was repaired and a murphy switch was installed to shut down the line when the line has high pressure.

Describe Area Affected and Cleanup Action Taken.*
Spill on location and into pasture starting at wellhead (40' x 150'), etech will clean-up per OCD/BLM regulation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 
Printed Name: Heather Dolphin	Approval Date: <u>11/10/15</u> Expiration Date: <u>N/A</u>
Title: Sr. Regulatory Specialist	Conditions of Approval: <input type="checkbox"/>
E-mail Address: heather.dolphin@memorialrd.com	Remediation per O.C.D. Rules & Guidelines
Date: 11/03/2015 Phone: 832-797-1334	SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 12/2/15

2RP-3381

* Attach Additional Sheets If Necessary