

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*0AB152A542546* OPERATOR  Initial Report  Final Report

Name of Company: COG Operating LLC *229137* Contact: Robert McNeill  
Address: 600 West Illinois Avenue, Midland TX 79701 Telephone No. 432-230-0077  
Facility Name: SRO State Com #43 Facility Type: Battery

Surface Owner: State Mineral Owner: API No. 30-015-41141

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	17	26S	28E	190'	North	990'	West	Eddy

Latitude 32.0492096 Longitude -104.1149597

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 9 bbls	Volume Recovered: 5 bbls
Source of Release: Oil Hauler	Date and Hour of Occurrence: 10/19/2015 5:30 pm	Date and Hour of Discovery: 10/19/2015 5:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
NOV 10 2015  
RECEIVED

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
While pulling a load of oil the truck driver overfilled his truck causing the oil to spill onto the location. A vacuum truck was able to recover 5 bbls of fluid. This release was caused by a third party oil hauler, Gibson Energy.

Describe Area Affected and Cleanup Action Taken.\*  
The impacted area remained on the pad near the LACT. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 11/12/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: November 1, 2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary

LATER THAN: *12/12/15*

*2RP-3360*