

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

NOV 11 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

## Release Notification and Corrective Action

NAB1532034732

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Southwest Royalties	Contact	Luis Gonzalez
Address	6-Desta Drive Suite 1100 Midland, Tx 79705	Telephone No.	(432) 661-4708
Facility Name	State 20 E #1	Facility Type	Oil Well
Surface Owner	State of NM	Mineral Owner	State of NM
		API No.	30-015-30969

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	20	17S	29E					Eddy

Latitude 32°49'26.30 Longitude 104°05'30.92

### NATURE OF RELEASE

Type of Release	Oil/Produced Water	Volume of Release	35	Volume Recovered	30
Source of Release	Flowline Leak	Date and Hour of Occurrence	11/09/15	Date and Hour of Discovery	11/09/15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Left a voicemail for Heather Patterson 11/10/15 @ 2:44pm (HP)		
By Whom?	Eric Garcia	Date and Hour	11/10/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Flowline leak. Crew was called out to repair the leak. Also, crew put up a fence around the spill area. Vacuum truck picked up approx. 30 barrels of oil. One call was made.

Describe Area Affected and Cleanup Action Taken.\*

The area affected is pasture. The spill measure approx. 60' X 10'. Crew put up a fence to prevent cattle from entering and a One Call was performed. Once the One Call clears the area will be cleaned up in accordance of NMOC Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: <i>DAVE DUNLAP</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: DAVE DUNLAP	Approval Date: 11/16/15	Expiration Date: N/A
Title: Prod Foreman	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: ddunlap@claytonwilliams.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: 11-10-15	Phone: 525-390-2062	LATER THAN: 12/17/15

\* Attach Additional Sheets If Necessary

2RP-3395