

**NM OIL CONSERVATION
ARTESIA DISTRICT**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 12 2015
Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1532026992 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: ROCKET FEDERAL COM #005H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-37778
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	26S	29E	180'	South	1980	East	Eddy

Latitude 32.0647278 Longitude -103.9692841

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 200 bbls	Volume Recovered: 0 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 10/28/2015 8:00 am	Date and Hour of Discovery: 10/28/2015 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Amanda Trujillo Davis	Date and Hour: Fri 10/30/2015 4:58 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused when a poly flowline was hit by a vehicle and damaged. The line was shut in and vacuum trucks were dispatched but were unable to recover any fluid.		
Describe Area Affected and Cleanup Action Taken.* The release is located in the pasture approximately 0.75 miles to the northeast of the well pad. The area of impact is approximately 225' x 150'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Amanda Trujillo Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>11/16/15</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: November 11, 2015 Phone: 575-748-6940	LATER THAN: <i>12/17/15</i>	

* Attach Additional Sheets If Necessary

2RP-3392