

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1532454352		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Apache Corporation 873		Contact: Bruce Baker			
Address: 2350 W Marland Blvd Hobbs, NM 88240		Telephone No. (432) 631-6982			
Facility Name: NFE water transfer line near Lee Federal # 27		Facility Type: Transfer line			
Surface Owner: Federal		Mineral Owner		API No. 30-015-32321	

LOCATION OF RELEASE

Unit Letter	Section 17	Township 17S	Range 31E	Feet from the 990'	North/South Line FSL	Feet from the 1750'	East/West Line FWL	County Eddy
-------------	---------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	----------------

Latitude Longitude

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 14 barrels of produced water	Volume Recovered: 10 barrels recovered
Source of Release: Transfer line	Date and Hour of Occurrence: 10/30/2015	Date and Hour of Discovery: 10/30/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker (BLM) and Mike Bratcher via email	
By Whom? Bruce Baker	Date and Hour: 11/2/2015 at 9:26 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NOV 19 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

A vehicle under carriage struck line resulting in line to rupture. The line was isolated and repaired. A vacuum truck was dispatched to pick up standing fluid. A barbed wire fence was installed to limit vehicle access over the line.

Describe Area Affected and Cleanup Action Taken.*

The majority of the release was contained on the lease road except approximately 1,000 square feet of pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Technician		Approval Date: 11/20/15	Expiration Date: N/A
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	
Date: 11/19/2015 Phone: (432) 631-6982		Attached <input type="checkbox"/>	

Mediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 12/20/15

* Attach Additional Sheets If Necessary

2RP-3410