District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

				Rele	ease Notifi	catio	n and Co	orrective A	ction	1				
3							OPERATOR Initial Rep.					\boxtimes	Final Repor	
3	Name of Comp			Contact Donna Huddleston										
	Address 3300 /													
٤	Facility Name	Parkv	vay Delawa	re Unit i	#513	Facility Typ	e Injection							
7	Surface Owner	BL	M		Mineral ()wner	BLM Lease No. NMNM88491X							
7		LOCATION OF RELEASE												
2000	, ,	ection 35	Township 19S	Range 29E	Feet from the	North	/South Line	Feet from the	East/\	Vest Line	County	Eddy		
2				La	titude		Longitud	le						
					NAT	URE	OF RELI	EASE						
ď	Type of Release		luced Water					Volume Recovered 0						
9	Source of Releas	e 2.5"	flanged Bal	on trunk i	ine valve.	Date and Hour of Occurrence Date and Hour of Discovery 2/25/09 7:30 AM 2/25/09 7:30 AM If YES, To Whom?								
	Was Immediate N	Notice G		Yes [No Not R	equired			& Jim					
	By Whom? Bill	y Whom? Bill Hearne												
	Was a Watercour													
☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*														
<u>a</u>	If a Watercourse	was Imp	oacted, Descri	be Fully.*										
1														
	David Consequence of the second of the secon													
	Describe Cause of Problem and Remedial Action Taken.* Cause: 2.5" flanged Balon trunk line valve failure (bottom of valve blow out) @ junction box.													
	Injection pumps	shut de	own on low ('900#) inj	ection pressure	. Estin	ated 50 bbls.	. Produced wate	ction box. oduced water spilled					
,	Describe Area Af											-		
		oction Station and north of PDU #513. Spill Area: 180' x 70' = 12,600 sq. ft. Itaminated soil and remediate with fresh soil.												
•														
1				ven above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and perport and/or file certain release notifications and perform corrective actions for releases which may endanger										
9	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
	should their opera or the environmen													
	federal, state, or lo													
ןנ						l	OIL CONSERVATION DIVISION							
1	Signature:	ignature:							1	/ /				
							Approved by District Supervisor:							
+	Printed Name:	TIIII RO	eu (agent ioi	St. Mary	/ Lanu)	-+								
	Title:	Tetra Te	ech				Approval Date: 11/4/15 Expiration Date: N/A							
]	E-mail Address:	<u>timoth</u>	v.reed@tetra	atech.con										
}	Date: 6/01/200)9		Phone:	432-682-4559				t,ne		Anached			
# L	Attach Additiona		s If Necessa		70L 00L-4000					-	711	-609	1/2	
											- 1-4	/		