District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABI	5337	52388	· 			OPERA?	ГOR		✓ Initia	al Report	F	Final Report	
Name of Co	ompany D	evon Energy			Contact Garry Michael, Production Foreman								
		Rivers Hwy	M 88220		Telephone No. 575-513-4895								
Facility Name Ross Ranch 10 Fed 1 SWD Facility Type SWD													
Surface Ov	vner Feder	rai	Mineral	Owner	Federal API No. 30-015-2960:								
LOCATION OF RELEASE													
						South Line	Feet from the		West Line County				
Н	H 10 26S 31E 1980					North 660			East Eddy				
Latitude: 32.059235486													
NATURE OF RELEASE													
Type of Release							Volume of Release Volume Recovered						
Produced Wa		10bbls 8bbls Date and Hour of Occurrence Date and Hour of I					COOVERY						
Disposal Pur		Date and Hour of Occurrence November 24, 2015 1:46 PM Date and Hour of Discovery November 24, 2015 1:46 PM											
Was Immed		If YES, To Whom?											
		Heather Patterson, OCD											
By Whom?	· · · · · ·	Jim Amos, BLM Date and Hour											
David Washington, Assistant Production Foreman							Heather Patterson, OCD November 24, 2015 1:05 PM						
***		Jim Amos, BLM November 24, 2015 1:35 PM If YES, Volume Impacting the Watercourse											
Was a Watercourse Reached? ☐ Yes ☑ No							N/A						
TC - 31/-4													
If a Watercourse was Impacted, Describe Fully.* N/A													
Describe Cause of Problem and Remedial Action Taken.*													
A stainless steel fitting on the salt water disposal pump leaked at the connection to the ball valve releasing approximately 10bbls produced water. All													
	valves on the stainless steel line connected to the pump were immediately closed to stop the release. The stainless steel fitting on the salt water disposal pump has been repaired.												
												 	
		l and Cleanup			st corner	of the location	on next to the salt	water d	isnosal nur	nn 10hhlsin	roduced	water was	
The spill was approximately 10'x 15' area located on the Southwest corner of the location next to the salt water disposal pump. 10bbls produced water was released and 8bbls were recovered with no fluid leaving location. Environmental agency will be contacted for remediation.													
7.11	'C- 41-44-	'- C	·		.1	b	111		سيم عام الم	nume to NIM	OCD =-1	las and	
							knowledge and u nd perform corre						
public health	or the envi	ronment. The	acceptant	ce of a C-141 repo	ort by the	NMOCD m	arked as "Final R	Report" d	loes not rel	ieve the oper	rator of I	liability	
should their	operations h	nave failed to	adequately	investigate and i	remediate	e contaminat	ion that pose a thive the operator of	reat to gr	round wate	r, surface wa	ter, hum	ian health	
		ws and/or regi		nance of a C-141	report a	oes not renev	e the operator of	respons	ibility for c	omphance w	/itti aliy t	otnei	
							OIL CON	SERV	ATION	DIVISIO	<u>N</u>		
Signature: Sheila Fisher							[]						
Printed Nam	a Chaila Fi	Approved by Environmental Specialist:											
Finited Ivain	e. Shena Fi	isilei		Approved by	- A A L C	ÌТ	17	1/2/	1				
Title: Field	Admin Sup	Approval Da	1e: 12315)	Expiration	Date: N	<u> </u>						
E-mail Addr	ess: Sheila.	Conditions of Approval:											
NM OIL CONSTERNACION Der O.C.D. Rules & Guidelines													
Attack Additional Chartes IC Normanian													
Attach Additional Sheets If Necessary DEC 0 2 2015 Attach Additional Sheets If Necessary DEC 0 2 2015												- 342	
					2 L V V	2 2013					<u></u>	9.01	