

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1534957206 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Fenton 7 Federal #1	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Unknown	API No. 30-015-27973

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	7	21S	28E	1980	North	1980	West	Eddy

Latitude 32.496615° Longitude -104.132350°

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 25 bbl oil 7 bbl pw	Volume Recovered 20 bbl oil
Source of Release Flare Stack	Date and Hour of Occurrence 12/10/2015 time unknown	Date and Hour of Discovery 12/10/2015 at 6:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (OCD), Jim Ames (BLM)	
By Whom? Amy Ruth	Date and Hour 12/10/2015 at 5:17 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 14 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Heater dump valves were found to have been closed at a unknown time over-night. Pumper re-opened the valves to direct fluids to the tanks.

Describe Area Affected and Cleanup Action Taken.*

The leak affected 840 ft² of pasture west of the tanks and 2,064 ft² of well pad. Vacuum truck recovered standing fluids and the impacted well pad area was fenced off to prevent traffic spread.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Approved by Environmental Specialist: 	
Title: Remediation Specialist	Approval Date: 12/15/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 12/14/2015 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/16/16	

* Attach Additional Sheets If Necessary

2RP-3451